



# NZDU01977 Dulux Weathershield Semi Gloss on Painted Precast, Tilt-up and Off Form Concrete [Exterior]

# Scope of Works

DULUX Weathersheild X10 Semi Gloss is a 100% acrylic self priming paint for exterior use. Its unique MaxiFlex Stretch Technology gives a tough, flexible finish for long life protection from the extremes of weather.

# **Substrate and Substrate Preparation**

#### **Substrate Notes**

For other masonry and cementitious substrates (such as concrete block) please use the Masonry substrate.

#### OFF FORM CONCRETE

Off-form Concrete is produced by placing suitable forms and shoring to hold the wet concrete into the required shape. Reinforcements are placed within or on the formwork to give concrete its strength. Once the formwork and shoring are removed the result is the off form concrete.

#### TILT UF

Tilt-up concrete is derived simply from the method of construction, wall panels are cast on a horizontal surface that then require lifting, and tilting vertically into their final position. Construction is commenced with the laying of the structures foundation and floor slab, wall panels are then cast on the floor one on top of each other in a stack arrangement.

#### PRF-CAST

Pre-Cast concrete are concrete panels that are cast on horizontal vibrating beds that are then cured in racks that are delivered to site that then require lifting, and positioned into their final position.

# **Substrate Preparation Notes**

#### ASSESS SUITABILITY

Inspect to determine the degree of deterioration of existing coatings. Identification of the existing coating is also very helpful in determining the repaint system. Check coating adhesion using the cross-cut adhesion test, carried out in various locations.

# REMOVE SURFACE CONTAMINANTS

Clean to remove all dirt, dust, efflorescence, laitance, powdery surfaces, mould and all other surface contaminants by using a suitable cleaning agent, such as Dulux Prep Wash and rinsing/water blasting clean with water. Water blasting will also give a good indication as to the coatings integrity. Efflorescence may also be removed with an acid treatment, followed by washing down the surface with water.

# REPAIR SURFACE IMPERFECTIONS

Prepare all areas that have poor adhesion, cracking, peeling and flaking by sanding, power sanding, scraping, wire brushing, grit blasting, burning off or chemical stripping as appropriate, to leave a clean surface. Feather edges of the surrounding sound paint to completely remove visual ridges and wash / dust off to remove debris. Any major design faults leading to structural failure must be corrected prior to repainting. Use an acrylic based patching compound with the addition of 10-20% fresh Portland cement to patch any surface defects.

# SANDING

Sand the entire cleaned coating to an even flat gloss level to provide a smooth, even surface and to provide a good key for the new coating system to adhere to. Ensure all sanding dust is removed prior to continuing.

# PRIME

Spot prime any exposed areas with a suitable water based primer, unless a more penetrating solvent based primer is required.

# ADDITIONAL NOTES:

• Ensure all previously painted enamel finishes are thoroughly abraded to ensure adequate adhesion of subsequent coating system.

# **Coating System Summary**

• 1st Coat Dulux PREP WASH

• Spot Primer Dulux 1 Step Prep Water Based Primer Sealer Undercoat

2nd Coat
 3rd Coat
 Dulux Weathershield Semi Gloss
 Julux Weathershield Semi Gloss





Coating System					
1st Coat — Dulux PREP WASH					
Coat Type 1st Coat		Datasheet NZDU00398 Dulux PREP WASH			
Read the full Datasheet details at <u>Dulux PREP WASH</u>					
Application Methods					
<b>#</b> Brush					
Broom Garden sprayer					
	Min		Max		Recommended
Theoretical Spread Rate (m²/L)	6		12		
Recoat Time **	n/a		n/a		n/a
Meets ECNZ V.O.C. Requirements?  Not Applicable					
Coating Application Details  Apply by broom or brush. Or by garden sprayer.  1. Add one part Dulux Prep Wash concentrate to one part water in a clean plastic bucket and mix well.  2. Test on a small inconspicuous area at recommended dilution to determine effectiveness and strength required.  3. Apply diluted Dulux Prep Wash solution to walls/roof/trim with a broom/brush or garden sprayer. Leave the solution on the surface until mould and mildew stains disappear or soften (approximately 10 minutes), avoiding allowing the solution to dry out. Scrub vigorously.  4. Rinse off the surface with water using a high pressure or garden hose and allow surface to dry. Surface may be slippery while wet (roof). Stubborn stains may require longer time, more vigorous scrubbing, or additional treatment. Severely stained surfaces may need a power washer, or treatment with undiluted Dulux Prep Wash concentrate.					
SDS Number 000000022880			SDS Link View SDS Link		
Spot Primer — Dulux 1 Step Pr	ep Water	Based Primer Sealer	Undercoat		
Coat Type <b>Spot Primer</b>		Datasheet NZDU00432 Dulux 1 S	itep Prep Water Bas	sed Primer Sealer	Undercoat
Read the full Datasheet details at <u>C</u>	ulux 1 Ste	p Prep Water Based Prin	ner Sealer Undercoa	a <u>t</u>	
Application Methods					
Air Spray 🛉 Airless Spray 📍 Brush 🚏 Roller					
	Min		Max		Recommended
Theoretical Spread Rate (m²/L)					14
Wet Film Per Coat (microns)					71
Dry Film Per Coat (microns)					31
Recoat Time **	2 Hours				
V.O.C. Level  < 40g/L untinted		Meets ECNZ V.O.C. Requirements?  Not Applicable			
Coating Application Details					





Brush, roller, conventional or airless spray.

ROLLER: Using a medium nap roller apply a full even coat direct from the container and finish by light parallel strokes with a dry roller. Stir contents thoroughly before and during use.

AIRLESS/CONVENTIONAL SPRAY: Suitable for application by all standard spray equipment. If necessary thin with up to 100ml per litre of water to aid atomisation.

BRUSH: Wet brushes with water prior to use to avoid clogging. Apply a full even coat direct from the container.

When painting exterior surfaces, ensure topcoat is applied no more than one week after application.

SDS Number DLXNZLEN002997	SDS Link View SDS Link

2nd Coat — Dulux Weathershield Semi Gloss				
Coat Type Datasheet NZDU00242		asheet DU00242 Dulux Weathershield Semi Gloss		
Read the full Datasheet details at <u>Dulux Weathershield Semi Gloss</u>				
Application Methods				
Air Spray Airless Spray F Brush Roller				
	Min	Max	Recommended	
Theoretical Spread Rate (m²/L)	16	16	16	
Wet Film Per Coat (microns)	63	63	63	
Dry Film Per Coat (microns)	25	25	25	
Recoat Time **	2 Hours	Indefinite		
V.O.C. Level < 60 g/L untinted		Meets ECNZ V.O.C. Requirements? Yes Total Volatile Organic Content (TVO accordance to the stated methodol Manuals. The TVOC content is theo of the known VOC values of the protection of the pro	ogy within Green Star Technical retically calculated as the sum total duct's raw material components. int plus additional low VOC tinter	

# Coating Application Details

Brush, roller, conventional and airless spray. Stir contents thoroughly before and during use with a broad flat stirrer, using an upward lifting action.

# Brush/Roller

Soak brush or roller in water before starting and use while still slightly damp. Thinning is usually not required.

# Airless or Conventional Spray

Suitable for application by all standard spray equipment. Apply wet even coats. If necessary thin with up to 100 ml/litre water to aid atomisation. Under hot or very windy conditions, up to 100 ml/litre of DULUX Hot Weather Thinner may be added to ease application. On previously painted surfaces, apply 2 coats of Weathershield. Some colours may require more than the recommended number of coats to achieve full opacity. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), when painting over contrasting colour, apply 1 coat of Dulux 1Step prep-coat.

# Within 1km of sea for galvanised iron, Zincalume

Apply one coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield. Preparation/coating system can vary depending on the quality and conditions of pre-primed timber/fibre cement, Colorbond® & Colorsteel® and tilt-up & precast concrete surfaces. For help and advice, please call Dulux Help & Advice on 0800 800 424 for specific guidance. Check the weather forecast. Do not paint on excessively cold or humid days. Exposure to rain or overnight dew whilst drying may result in the coating being damaged or removed. If painting during the hottest time of the day, cool the surface by hosing before painting and paint on the shady side of the house.

# Steel/wrought iron

Apply 2 coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield.

Bare surfaces including brick, masonry, fibre cement, Zincalume





Apply 3 coats of Weathershield.

#### Galvanised iron

Apply 3 coats of Weathershield. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), apply 1 coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield.

# For Zincalume/galvanised iron roofs

Apply 3 coats of Weathershield. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), apply 1 coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield.

# Bare unpainted timber

Apply 3 coats of Weathershield. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), for improved resistance to cracking on hardwoods (eg Mt Ash, Oak), apply a coat of Dulux 1Step Prepcoat prior to the application of two topcoats of Weathershield. Professional Painters refer to Duspec Specification Sheets to qualify for guarantee.

SDS Number	SDS Link
DLXNZLEN003378	<u>View SDS Link</u>

3rd Coat — Dulux Weathershield Semi Gloss				
Coat Type 3rd Coat	Datasheet NZDU00242 Dulux W	eathershield Semi Gloss		
Read the full Datasheet details at <u>Dulux Weathershield Semi Gloss</u>				
Application Methods				
Air Spray Airless Spray P Brush Roller				
	Min	Max	Recommended	
Theoretical Spread Rate (m²/L)	16	16	16	
Wet Film Per Coat (microns)	63	63	63	
Dry Film Per Coat (microns)	25	25	25	
Recoat Time **	2 Hours	Indefinite		
V.O.C. Level  < 60 g/L untinted		Meets ECNZ V.O.C. Requirements?  Yes  Total Volatile Organic Content (TVO accordance to the stated methodolo Manuals. The TVOC content is theor of the known VOC values of the pro These materials include the base par required for non-factory packaged of	ogy within Green Star Technical retically calculated as the sum total duct's raw material components. int plus additional low VOC tinter	

# Coating Application Details

Brush, roller, conventional and airless spray. Stir contents thoroughly before and during use with a broad flat stirrer, using an upward lifting action.

# Brush/Roller

Soak brush or roller in water before starting and use while still slightly damp. Thinning is usually not required.

# Airless or Conventional Spray

Suitable for application by all standard spray equipment. Apply wet even coats. If necessary thin with up to 100 ml/litre water to aid atomisation. Under hot or very windy conditions, up to 100 ml/litre of DULUX Hot Weather Thinner may be added to ease application. On previously painted surfaces, apply 2 coats of Weathershield. Some colours may require more than the recommended number of coats to achieve full opacity. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), when painting over contrasting colour, apply 1 coat of Dulux 1Step prep-coat.

Within 1km of sea for galvanised iron, Zincalume





Apply one coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield. Preparation/coating system can vary depending on the quality and conditions of pre-primed timber/fibre cement, Colorbond® & Colorsteel® and tilt-up & precast concrete surfaces. For help and advice, please call Dulux Help & Advice on 0800 800 424 for specific guidance. Check the weather forecast. Do not paint on excessively cold or humid days. Exposure to rain or overnight dew whilst drying may result in the coating being damaged or removed. If painting during the hottest time of the day, cool the surface by hosing before painting and paint on the shady side of the house.

#### Steel/wrought iron

Apply 2 coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield.

#### Bare surfaces including brick, masonry, fibre cement, Zincalume

Apply 3 coats of Weathershield.

#### Galvanised iron

Apply 3 coats of Weathershield. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), apply 1 coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield.

# For Zincalume/galvanised iron roofs

Apply 3 coats of Weathershield. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), apply 1 coat of Dulux All Metal Primer followed by 2 topcoats of Weathershield.

# Bare unpainted timber

Apply 3 coats of Weathershield. For Weathershield Chromamax Pigment Bases (True Red, Bold Yellow, Orange, Blue and Extra Bright bases), for improved resistance to cracking on hardwoods (eg Mt Ash, Oak), apply a coat of Dulux 1Step Prepcoat prior to the application of two topcoats of Weathershield. Professional Painters refer to Duspec Specification Sheets to qualify for guarantee.

SDS Number	SDS Link
DLXNZLEN003378	View SDS Link

#### Coating System Notes

\* Practical Spreading Rate will vary from the quoted Theoretical Spreading Rate due to factors such as method and condition of application and surface roughness. \*\* Recoat times are quotes for 25°c and 50% relative humidity, these may vary under different conditions.

# Disclaimer

This Specification is copyright to DuluxGroup (Australia) Pty Ltd and/or DuluxGroup (New Zealand) Pty Ltd (collectively, 'Dulux'). It may not be varied or altered without the prior written consent of Dulux, and if it is, Dulux has no responsibility or liability for those variations.

Unless Dulux has provided you with a customised, project-specific specification, this Duspec+ document does not represent that any particular product or product system will be suitable for your project.

Any information provided in this Duspec+ is given in good faith and is believed by Dulux to be correct at the time of publication. Products and coating systems can be expected to perform as indicated in this Duspec+ document, provided the substrate is in good condition, the coatings are applied by a suitably experienced and skilled applicator, and the preparation, application and maintenance is followed strictly as set out in this Duspec+ document, and as recommended on the applicable Dulux Product Data Sheet and Safety Data Sheets for the relevant products (available from <a href="https://www.duspecplus.co.nz">www.duspecplus.co.nz</a>). Climatic conditions at application time can affect Duspec+ documentation suitability and product performance.

The correct colour or colour match is the responsibility of the applicator. Colours will change over time and Dulux does not guarantee that the same colour newly mixed will match a colour applied earlier which has been subjected to weathering or other change elements. No product colour is guaranteed against colour change.

Where any liability of Dulux in respect of this Specification cannot by law be excluded, Dulux's liability is limited, as permitted by law and at Dulux's option, to resupply of the relevant products or services or to reimbursing the cost of those products or services.

WHERE LEAD MAY BE PRESENT: The asset manager is responsible for verifying the presence of lead and determining whether to remove or encapsulate the lead. If lead is present, the work must be done in strict accordance with AS/ NZS 4361 Parts 1 and 2 and Worksafe Australia or New Zealand guidelines.