



NZDU01088 Dulux Aquanamel Semi Gloss on New Non-Ferrous Metals [Interior]

Scope of Works

DULUX Aquanamel Semi Gloss is a premium quality water based interior acrylic enamel, that dries to a tough finish. This product is so resistant that common marks are able to be removed virtually without trace. It resists knocking, chipping and yellowing and is highly recommended for doors, architraves, timber trim, walls and skirting boards as an alternative to enamels, and is ideal for bathrooms, kitchens and laundries.

Substrate and Substrate Preparation

Substrate Notes

This is a generic non-ferrous metal substrate. Please see the respective substrate for: steel, galvanised steel, precoated sheet steel . Other specialty metal substrates may also not be covered by this substrate.

ALUMINIUM & ALLOYS

Aluminium and its alloys rapidly oxidise on exposure, forming a chemically inert, protective layer that protects the metal from further corrosion.

Aluminium and its alloys may be extremely smooth or contaminated with greases, oils and foreign matter leading to poor paint adhesion and reduced lifetime. Careful cleaning and thorough abrasion of the surface must be carried out prior to painting to ensure maximum coating performance.

ANODISED ALUMINIUM

Anodising is an electro-chemical process which physically alters the surface of the metal to produce a very smooth, tough, dense, invisible oxide layer on the surface. The aluminium surface is 'passivated' and sealed and therefore unable to bond with any organic coating, including powder coatings unless proper surface preparation is carried out to ensure adequate adhesion of the applied finish.

COPPER

Copper metal has a dull brown metallic lustre but will oxidise to the familiar chalky green patina often seen on copper domes on heritage buildings. This green patina must be completely removed prior to painting.

BRASS

Brass is an alloy (blend) of copper and zinc. Brass can be polished to a bright, shiny, lustrous metallic dark gold appearance but is prone to tarnishing (surface corrosion), particularly on contact with skin, and therefore should not be handled with bare hands. Brass is very smooth and may be coated with oils leading to poor paint adhesion and reduced lifetime. Careful cleaning and thorough abrasion of the surface must be carried out prior to painting to ensure maximum coating performance.

BRONZE

Bronze is an alloy (blend) of copper and tin and has a shiny, lustrous brown metallic appearance that is prone to tarnishing (surface corrosion) to a dusty green patina with time. Bronze is generally quite smooth and may be contaminated with oils leading to poor paint adhesion and reduced lifetime. Careful cleaning and thorough abrasion of the surface must be carried out prior to painting to ensure maximum coating performance.

Substrate Preparation Notes

DOMESTIC

CLEAN

Remove all surface contamination such as oil, grease or dirt by washing with an alkaline detergent, such as Dulux Prep Wash, and rinse with fresh potable water.

ABRADE

Thoroughly abrade the non ferrous metal surface to establish a mechanical key by scouring the surface with a nylon scouring pad, scotch-brite pad or power tool using a 50/50 mix of methylated spirits and water as a lubricant. Ensure all dust is removed prior to continuing.

DRY

Wipe dry using a clean cloth and allow to dry completely.

PRIME

Apply a suitable primer over the entire area as soon as possible to reduce the risk of corrosion.

INDUSTRIAL

CLEAN

Remove all surface contamination such as oil, grease or dirt by washing with an alkaline detergent, such as Dulux Prep Wash, and rinse with fresh potable water. Refer to AS1627.1 Part 1.4.4 - 1.4.6.

ABRADE

Dry abrasive "brush blast" clean (whip blast) the surface using a non-metallic abrasive such as garnet. The abrasive size and blast pressure shall be such that all oxidation products and other surface contaminants are completely removed and that the surface is profiled to provide a suitable key for adhesion of the coating system.

If the item being painted is not suitable for brush blasting (eg sheet metal or thin extrusions) then use non-metallic abrasive sanding pads to remove any existing oxidation and provide a suitable key for coating adhesion. Note that this preparation method is likely to be less effective than brush blasting and should only be used where brush blasting is not suitable.





Remove all spent abrasive and residual dust by using dry compressed air or, preferably, vacuum cleaning prior to application of the coating. Avoid handling abraded metal with bare hands.

REPAIR SURFACE IMPERFECTIONS

Coating System Summary

• 1st Coat

• 2nd Coat

Inspect the surface prior to coating to ensure no contamination is present and no surface defects exist. If either contaminants or defects are present, rectification is required before any coating is applied.

PRIME

Apply first or primer coat as soon as practical after preparation and before the surface oxidises or becomes re-contaminated.

Dulux 1 Step Prep Water Based Primer Sealer Undercoat

Dulux Aquanamel Semi Gloss

3rd Coat Dulux Aquanamel Semi Gloss						
Coating System						
1st Coat — Dulux 1 Step Prep	Water Base	ed Primer Sealer Und	dercoat			
31		Datasheet NZDU00432 Dulux 1 Step Prep Water Based Primer Sealer Undercoat				
Read the full Datasheet details at	<u>Dulux 1 Step</u>	Prep Water Based Prin	ner Sealer Undercoat			
Application Methods						
Air Spray 🛉 Airless	Spray 📮	Brush Rol	ler			
	Min		Max	Recommended		
Theoretical Spread Rate (m²/L)				14		
Wet Film Per Coat (microns)				71		
Dry Film Per Coat (microns)				31		
Recoat Time **	2 Hours					
V.O.C. Level < 40g/L untinted			Meets ECNZ V.O.C. Requiremer Not Applicable	nts?		
Coating Application Details Brush, roller, conventional or airless ROLLER: Using a medium nap rolle Stir contents thoroughly before and AIRLESS/CONVENTIONAL SPRAY: to aid atomisation. BRUSH: Wet brushes with water pri When painting exterior surfaces, er	r apply a full e d during use. Suitable for ap ior to use to av	oplication by all standar void clogging. Apply a	d spray equipment. If necessary th	in with up to 100ml per litre of water		
SDS Number DLXNZLEN002997			SDS Link View SDS Link			
2nd Coat — Dulux Aquaname	l Semi Gloss					
Coat Type 2nd Coat		Datasheet NZDU00233 Dulux Aquanamel Semi Gloss				
	1					

Read the full Datasheet details at <u>Dulux Aquanamel Semi Gloss</u>





Application Methods						
Air Spray 🛉 Airles	s Spray 🕴 Brush 🌹 Rol	ler				
	Min	Max	Recommended			
Theoretical Spread Rate (m²/L)	16	16	16			
Wet Film Per Coat (microns)	63	63	63			
Dry Film Per Coat (microns)	22	22	22			
Recoat Time **	2 Hours	Indefinite				
V.O.C. Level <53 g/L inclusive of Dulux Low VOC tinter.		Meets ECNZ V.O.C. Requirements? Yes Total Volatile Organic Content (TVOC) values are calculated in accordance to the stated methodology within Green Star Technical Manuals. The TVOC content is theoretically calculated as the sum total of the known VOC values of the product's raw material components. These materials include the base paint plus additional low VOC tinter required for non-factory packaged colours.				
Coating Application Details * Some colours may require more than the recommended number of coats to achieve full opacity. Stir contents thoroughly before and during use with a broad flat stirrer using an upward lifting action. Brush, roller or HVLP spray Brush-Roller Brush- Dulux Professional brushes are recommended. Apply evenly, dividing area into patches about 50-60 square centimetres. Paint one patch at a time working back into previously applied paint. Finally lay off each patch with light vertical strokes again lapping lightly into previously painted patches. On wall areas use a 5-9mm nap synthetic roller to achieve the smoothest finish. Generally thinning is not recommended, however, under hot conditions DULUX Hot Weather Thinner should be added to improve application performance to maximum of 50 ml per litre. Airless/Conventional Spray Suitable for application by conventional or airless spray equipment. Up to 100mL/L of water may be added for application by conventional spray, up to 30mL/L of water for airless spray, and up to 5mL/L for HVLP spray, to aid atomisation. Wagner recommendation: F230 Aircoat recommended. Tip: 211 for archs and trim, 411 for doors Pressure: 1100 PSI 1-1.5 at the bar at the gun Graco recommendation: Air Assisted Airless. Tip: 210 or 310						
SDS Number DLXNZLEN003191		SDS Link View SDS Link				

3rd Coat — Dulux Aquanamel Semi Gloss					
Coat Type 3rd Coat	Datasheet NZDU00233 Dulux Aquanamel Semi Gloss				
Read the full Datasheet details at <u>Dulux Aquanamel Semi Gloss</u>					
Application Methods Air Spray Airless Spray	Brush Roller				





	Min	Max	Recommended
Theoretical Spread Rate (m²/L)	16	16	16
Wet Film Per Coat (microns)	63	63	63
Dry Film Per Coat (microns)	22	22	22
Recoat Time **	2 Hours	Indefinite	
V.O.C. Level <53 g/L inclusive of Dulux Low V	OC tinter.	accordance to the state Manuals. The TVOC co of the known VOC valu	Content (TVOC) values are calculated in ed methodology within Green Star Technical entent is theoretically calculated as the sum totales of the product's raw material components. The base paint plus additional low VOC tinter
Brush, roller or HVLP spray Brush/Roller Brush- Dulux Professional brushes Apply evenly, dividing area into pa		re centimetres. Paint one patch at a tin	ne working back into previously applied paint.
		pping lightly into previously painted pa	
On wall areas use a 5-9mm nap syl	,		
Generally thinning is not recomme performance to maximum of 50 ml		ot conditions DULUX Hot Weather Thir	nner should be added to improve application
Airless/Conventional Spray Suitable for application by conven- up to 30mL/L of water for airless sp			oe added for application by conventional spray,
Wagner recommendation: F230 Ai Tip: 211 for archs and trim, 411 fo Pressure: 1100 PSI 1-1.5 at the bar at the gun			
Graco recommendation: Air Assist	ed Airless.		

Coating System Notes

Pressure: 1100 PSI

DLXNZLEN003191

SDS Number

* Practical Spreading Rate will vary from the quoted Theoretical Spreading Rate due to factors such as method and condition of application and surface roughness. ** Recoat times are quotes for 25°c and 50% relative humidity, these may vary under different conditions.

SDS Link

View SDS Link





Disclaimer

This Specification is copyright to DuluxGroup (Australia) Pty Ltd and/or DuluxGroup (New Zealand) Pty Ltd (collectively, 'Dulux'). It may not be varied or altered without the prior written consent of Dulux, and if it is, Dulux has no responsibility or liability for those variations.

Unless Dulux has provided you with a customised, project-specific specification, this Duspec+ document does not represent that any particular product or product system will be suitable for your project.

Any information provided in this Duspec+ is given in good faith and is believed by Dulux to be correct at the time of publication. Products and coating systems can be expected to perform as indicated in this Duspec+ document, provided the substrate is in good condition, the coatings are applied by a suitably experienced and skilled applicator, and the preparation, application and maintenance is followed strictly as set out in this Duspec+ document, and as recommended on the applicable Dulux Product Data Sheet and Safety Data Sheets for the relevant products (available from www.duspecplus.co.nz). Climatic conditions at application time can affect Duspec+ documentation suitability and product performance.

The correct colour or colour match is the responsibility of the applicator. Colours will change over time and Dulux does not guarantee that the same colour newly mixed will match a colour applied earlier which has been subjected to weathering or other change elements. No product colour is guaranteed against colour change.

Where any liability of Dulux in respect of this Specification cannot by law be excluded, Dulux's liability is limited, as permitted by law and at Dulux's option, to resupply of the relevant products or services or to reimbursing the cost of those products or services.

WHERE LEAD MAY BE PRESENT: The asset manager is responsible for verifying the presence of lead and determining whether to remove or encapsulate the lead. If lead is present, the work must be done in strict accordance with AS/ NZS 4361 Parts 1 and 2 and Worksafe Australia or New Zealand guidelines.